

# Stock Table Throw Care Sheet

Product meets National Fire Product Association (NFPA) standard 701 for Flame Resistance.

## Handling Tips

1. Wrinkles can be removed with cool iron or fabric steamer.
2. For storing graphics please remove from plastic packaging that was provided and keep fabric in cool/dry place.  
Fabric should NOT be stored when damp or wet.
3. Do NOT iron directly on printed sections of fabric.

## Washing

1. Your fabric graphic can be machine washed. Use MILD soap and cool water. Tumble dry medium low - medium heat.
2. Fabric must be COMPLETELY dry prior to storing.
3. **DO NOT DRY CLEAN**

## Stain Treatment


1. Treat stain from backside of fabric.
2. Remove as much of debris as possible with a soft bristle brush (do NOT rub too hard)
3. Use a clean, lint-free white cloth. Lightly pat the stain from the outside moving in (to keep stain from spreading)
4. If a cleaning solution is used, rinse the area well with water to ensure NO solution is left on fabric.
5. Most stains can be treated with household fabric stain removers. It is ALWAYS important to test how the solution will react to the fabric. This can be tested by dabbing solution to a small corner of the fabric. Most household cleaners will provide treatment instructions depending on the type of stain.



Wrinkles can be removed from fabric with a cool iron or steamer. ONLY iron/steam on **BACK** side of fabric. Do NOT iron on printed section.



Fabric can be machine washed - use cold water, delicate cycle.



Do NOT bleach fabric



Tumble dry, medium low to medium heat.

**DO NOT DRY CLEAN**